

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/30/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/17/12 – 0700, 05/31/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, Texas
8. Activity Log			
Time	Major Events		
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • MP7.89 LDB, observed woody debris removal crew. • MP7.89 LDB, sheen observed when the boat docked along the shoreline. • MP8.48, Sheen observed within boom. • MP8.75 RDB boom, no sheen observed. • MP9.75 RDB, poling crew observed. • MP10.75 sediment control trap, water levels receding. • MP10.75, sheen observed within the boom. • MP10.75, poling crew observed. • MP10.0 C3.2 boat launch, sheen observed around docking boats. • Ceresco Dam, sheen and debris collecting at boom. • Ceresco Dam, sheen observed between two booms. • Ceresco Dam, sheen observed down stream of boom. • Ceresco Dam, tar glob bound to vegetation flowing over dam. • Ceresco Dam, sheen observed flowing over dam. • Ceresco Dam, owner is having turbines removed. • C0.4 Boat launch, sheen observed bound in vegetation. • MP37.75, Poling crew observed just below E4 boom. • Morrow Lake Dam velocity study observed. • MP38.75 north shore Morrow Lake, sheen observed. • Morrow Lake, sweep boat responding to sheen observed. • MP38.25 Morrow Lake, sheen observed. • MP38.00 Morrow Lake north cove, sheen observed. 		
	Additional observations: None		
15:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			